

To: rlaw@demaximis.com[]
Cc: []
Bcc: []
From: CN=Stephanie Vaughn/OU=R2/O=USEPA/C=US
Sent: Wed 2/6/2013 2:01:23 PM
Subject: Fw: Rm 10.9 oversight February 5, 2013

Rob -- Please give me a call when you can. I think it was pretty clear that they weren't supposed to start work until Tuesday.

Thanks

----- Forwarded by Stephanie Vaughn/R2/USEPA/US on 02/06/2013 08:42 AM -----

From: "Kirchner, Scott" <KirchnerSF@cdmsmith.com>
To: Stephanie Vaughn/R2/USEPA/US@EPA
Cc: "Buckrucker, Elizabeth A NWK" <Elizabeth.A.Buckrucker@usace.army.mil>, "Budney, Sharon" <BudneySL@cdmsmith.com>, "Tsang, Frank" <TsangC@cdmsmith.com>, "Rakowski, Jeffrey" <RakowskiJJ@cdmsmith.com>, "Molnar, George" <MolnarGC@cdmsmith.com>
Date: 02/06/2013 07:42 AM
Subject: FW: Rm 10.9 oversight February 5, 2013

Stephanie,

On Tuesday February 5, 2013, CDM Smith oversight staff observed sediment coring in support of the RM 10.9 removal action program. Two locations, RM10.9D-0338 and -0351, were sampled; however, crews were unable to collect all the needed cores at -0351, and plan to return and complete on Wednesday the 6th.

During sampling activities, an outfall behind Lyndhurst Pumpstation 4 opened up and discharged during sampling at location RM10.9D-0351 which was located approximately 100' southwest.

Field crews informed oversight staff that location RM10.9D-0350 was sampled sometime on Monday the 4th after mobilization. Oversight staff were unaware of CPG's plans to conduct any sampling on Monday so no oversight was performed at that location.

Sincerely

Scott F Kirchner, CHMM | Project Manager | CDM Smith
110 Fieldcrest Avenue, #8, 6th Floor | Edison, NJ 08837 | phone/fax (732) 590-4677 | cell (732) 713-6824